~ .x-	A CONTRACTOR OF THE PARTY OF TH	Engineerli		Crawing Title		MEMORY DATA		مزجاري	Xerox Corporation El Segundo, Californ. XEROX			
1	EO i	[] Immediate	Effectivity	- ATD2/)			DAM	MIPC.	Drawing Number 2/63/6		2	Chg. Ltr.
	Reserve Serial No./Date Variation Next Production			Dist. Code DCR		No. DCR Date Model No 2-22-77 ACTO			Noxl Assembly No. Shoet			1
	Affected by This Chango					Disposition of Existing P				arts Lowest Acc		
	Constant	Yes No	Dwg. No.	Other Dwgs.		Status	Return To Stock	Rework	Uso	Scrap	Revision L	
	Spare Parts Tooling					On Order		·/	:		Mandatory	
	Test Procedures					In Process			Pri Re	ļ	Prior Revisions Field Info.	
	Test Equipment	<u> </u>				in Stock in Next Assy.		V				
	Programs	ää	. 			in Fjeld				 		only-
	Tech. Publication					Refurbishment				Lowest fiel	d	
	Reason For Change (Il reason is Design Error or Reliability, describe s					1		<u> </u>		<u></u>	usage level	
D	Design Error Drawing Error Producibility Maintainability Reliability Cost Reductio	y on	HOO WAS: 74		Rowork	instructions	· · · · · · · · · · · · · · · · · · ·		·			-
	WL ITEM	NAS: 434,	45= 434. WITH 74400. 10 PLACES.							ci=		
	MC ITEM MC ITEM	514-AGIOD 516-AGIOD	USE SOCKET PN 514-AGIID INPLACE OF PN 514-AGIOD, PB 55 PLACES. ASE SOCKET PN 516-AGIID INPLACE OF									
	SH 5 LOO	5132	. V	se sock	9/	, 516-	-AG10	D INP	PLACE	es ,		
		MATERIZE	Test P	rocedure to Verity		•	FNOISE			TO SEA		
	Meskemuras 1216-1(127/4)	2-77-77	nock Date	Floid/Mig.	Α	Date	Proj. Engr	11	2/27/	77/06	Hewar	A 2/22/17
		• •			Æ							